

Wear parts: PCD, PCBN, tungsten carbide and ceramics

Complete Wearless and Wear Parts designs for workpiece support, bearing manufacturing and measuring applications.



EHWA Europe GmbH

www.ehwadia.de

Contents

Contact surfaces with a defined function	3
Material and contact surface	5
Applications and component families	6
Bearing backing plates: five Wearless designs	8
V-blocks: seven Wearless designs	9
Sliding shoes: five Wearless designs	9
Dead centre	10
Special gauges and measuring contacts	10
Guide blades and work-rest blades	11
Further designs from Wear Parts	12
Discuss your contact task	13

Contact surfaces with a defined function


Wearless and Wear Parts for workpiece support, bearing manufacturing and measuring applications

EHWA DIAMOND - since 1975

EHWA presents wear parts that support, guide or contact workpieces for measurement. The Wearless and Wear Parts families comprise backing plates, V-blocks, sliding shoes, dead centres, special gauges and guide blades. The programme combines application-specific geometries with wear-resistant contact materials.

Selection considers contact position, workpiece, machine and surface requirements. The illustrated forms and actual product photographs show different designs; the component drawing defines the specific function and mounting. Wearless remains the product name.


Round support form



Schematic illustration

Schematic round support form from the Wearless cover illustration.


Block-shaped contact component



Schematic illustration

Schematic block-shaped contact component from the Wearless cover illustration.

Support form with multiple contact surfaces



Schematic illustration

Schematic support form with multiple contact surfaces from the Wearless cover illustration.



Wear part designs shown in the Wear Parts cover photograph.


Material and contact surface

The Wear Parts document identifies four material families: polycrystalline diamond (PCD), PCBN, tungsten carbide and ceramics. Material selection follows the actual contact task.


Material family	Relationship described in the document
PCD	Wear resistance for longer useful life; polished contact surfaces to reduce friction
PCBN	Identified as a material family for wear parts; actual design matched to the application
Tungsten carbide	Identified as a material family for wear parts; actual design matched to the application
Ceramics	Chemical resistance as a feature supporting reduced chemical wear and surface scratching

EHWA describes PCD wear resistance as a basis for longer useful tool life. A polished PCD contact surface can reduce friction. The document gives a minimum Ra value of 0.02 without specifying a unit. Target roughness, unit and measurement conditions are defined together for the actual design.

For ceramics, EHWA describes chemical resistance and its benefit to the contact surface and workpiece finish. The appropriate ceramic design is matched to the material pair, loading and process media. Precise customised geometries are available on request.



Example of a polished PCD contact surface.



Example contact component with a ceramic contact surface.

Applications and component families

Application	Components or tasks listed in the programme
Centreless grinding machines	Support and guide blades for centreless grinding
Cylindrical grinding machines	Support and contact components matched to the machine and workpiece
Measuring probes and metrology	Gauges and measuring contacts
Bearing manufacturing	Support and contact components matched to component geometry
Other machines	Customised contact geometries

The Wear Parts sheet lists Centerless blades, Sliding shoes & V-blocks as work-rest parts, Backing plates for bearing manufacturing and Gauges as measuring probes. The Wearless illustrations supplement these families with dead centres and further backing plate, V-block, shoe, gauge and guide blade designs.



Bearing and machine application in the Wear Parts sheet:
gear/bearing application image.



Bearing and machine application in the Wear Parts sheet:
bearing example 1.



Bearing and machine application in the Wear Parts sheet:
bearing example 2.



Bearing and machine application in the Wear Parts sheet:
bearing example 3.



Bearing and machine application in the Wear Parts sheet:
roller bearing application image.

Bearing backing plates: five Wearless designs

The Wearless Bearing backing plate group shows five backing plate forms. These include round contact faces, ring-shaped contact areas and segmented contact surfaces. Holes, mounting faces and contact area positions remain visible in the illustrations. The design is matched to the relevant bearing processing task.



Wearless: bearing backing plate design 1.



Wearless: bearing backing plate design 2.



Wearless: bearing backing plate design 3.



Wearless: bearing backing plate design 4.



Wearless: bearing backing plate design 5.

V-blocks: seven Wearless designs

The V-block group shows different block-shaped workpiece supports. The illustrations include individual and opposing contact surfaces, fitted contact pieces and different mounting arrangements. Geometry is matched to the workpiece and machine mounting.



Wearless: V-block design 1.



Wearless: V-block design 2.



Wearless: V-block design 3.



Wearless: V-block design 4.



Wearless: V-block design 5.



Wearless: V-block design 6.



Wearless: V-block design 7.

Sliding shoes: five Wearless designs


The Shoe group contains five design images with different contact positions. These include elongated forms, compact block forms and a narrow elongated design with mounting openings. The contact surface is matched to the actual workpiece surface being supported or guided.



Wearless: sliding shoe design 1.



Wearless: sliding shoe design 2.



Wearless: sliding shoe design 3.



Wearless: sliding shoe design 4.



Wearless: sliding shoe design 5.

Dead centre

The Wearless document shows a fixed centre under the name Dead center. The illustrated contact area is at the tip. Mounting, workpiece contact and material design are defined for the specific machine; the illustration contains no additional installation dimensions.



Wearless: dead centre with a contact area at the tip.

Special gauges and measuring contacts

The Special gauges group shows five design images: cylindrical and flanged forms, elongated probing forms, an angled form and a threaded design with a measuring contact. Measurement function is matched to the drawing, contact position and required accuracy.



Wearless: special gauge design 1.



Wearless: special gauge design 2.



Wearless: special gauge design 3.




Wearless: special gauge design 4.



Wearless: special gauge design 5.

Guide blades and work-rest blades

The Wearless Guide blade group shows three elongated blade forms with different contact strips and mounting features. All three illustrations are retained. Corresponding blade forms are presented in the Wear Parts overview as Centerless blades for centreless grinding.



Wearless: all three illustrated guide blades, including contact strips and mounting features.

Further designs from Wear Parts

The overview shows round and block-shaped support/contact components, gauges and work-rest blades. Basic forms can fulfil different contact tasks depending on the design. The final mapping to a sliding shoe, V-block or backing plate therefore follows the specific drawing and application.



Bearing examples from the Wear Parts sheet.




Various wear part designs with fitted contact surfaces.



Three support/guide blades from the Wear Parts overview.



Round support and contact components from the Wear Parts overview.



Block-shaped support and contact components from the Wear Parts overview.



Gauge and measuring contact designs from the Wear Parts overview.

Discuss your contact task

Provide the component drawing, workpiece material, machine, mounting and contact position. Add loading, process media, required surface parameters and desired useful life. For replacement parts, existing mounting dimensions, contact marks and the current wear pattern support the discussion.

A suitable design combines wear-resistant contact surfaces with geometry matched to the machine. Comparison considers dimensional change of the wear part, workpiece surface condition and useful life together.

EHWA Europe: info@ehwadia.de · +49 6173 997780

Editorial edition: 13 October 2026. Technical basis: the complete EHWA Wearless document, four pages, and Wear Parts document, two pages. Wear Parts bears the printing note 06/2024.